

Sierra Vista
 4711 S Highway 92
 1-800-559-9291 Phone
 520-458-9293 Fax



COMMERCIAL POOL CARE DIVISION

Northwest
 6320 N Oracle Rd
 520-797-2299 Phone
 520-797-9293 Fax

Central
 2512 N Campbell Ave
 520-795-8240 Phone
 520-327-1142 Fax

Main Office/Eastside
 7960 E 22nd St
 520-886-1211 Phone
 520-886-6364 Fax

Northeast
 9155 E Tanque Verde Rd
 520-749-9155 Phone
 520-760-0035 Fax

| PATIO'S | | RAINBOW IN-LINE CHLORINATOR | | MANUFACTURER | |
|----------|----------|--|--|--------------|--|
| NUMBER | ITEM KEY | MODEL #320 | | NUMBER | |
| 28-0040 | 1 | Cap Wrench | | R172052 | |
| 28-0027 | 2 | 3" Threaded Cap | | R172008 | |
| 26-0283 | 3 | Cap O-Ring | | R172009 | |
| | 4 | #320 Body Only | | R172257 | |
| | 5 | Lock Screw | | R172078 | |
| | 6 | Check Valve | | R172331 | |
| SP3-5720 | 7 | Diverter - Tee, 1-1/2 NPTx2" Slip | | R172317 | |
| SP3-5668 | 8 | 1/2" MPT Nipple | | R172256 | |
| 28-2006 | 9 | 1/2" Chlorine Control Valve | | R172086 | |
| 28-0022 | 10 | 1/2" NPT x Tube 90 ELL w/Nut Only | | R172272 | |
| SP3-6505 | 10A | Compression Nut Only | | R172274 | |
| | 11 | 5/8" O.D. Tube | | R172091 | |
| 17-0684 | 12 | 2" x 1-1/2" Bushing, (For 1-1/2" PVC Only) | | DUR437251 | |
| SP1-6148 | 13 | Spa Chamber | | R172037 | |
| 14-0002 | 14 | Silicone Lubricant | | 650A | |
| 28-0071 | 15 | Screen | | R172255 | |
| | 16 | 1/2" MPT PVC Plug | | R172134 | |
| 28-0052 | 17 | 5/8" O.D. x 18" Tube (Sold by the Foot) | | R172253 | |
| 26-0444 | 18 | Bottom O-Ring, Only (O-444) | | R172319 | |
| 28-2000 | 19 | 1-1/2" Check Valve | | R172288 | |

